

CALIPER ASSEMBLY, Modification to Bridge Bolt (#3)

The Factory has increased the diameter and thread pitch of the above bolt. Consequently, this changes the Assembly Part Number, etc.

AFFECTED MACHINES

The change became effective on production at Frame No. 108293 ~.

PARTS ORDERING

Please make the following corrections/additions to the XS2 Parts List.



306-25826-00 → 306-25826-01 (BRIDGE BOLT #3)
 (M5x0.8x16.0) (M8x1.0x19.5)

Ref. No.	Old Parts No.	New Parts No.	Parts Name	Q'ty	Interchangeable
35-0-5	*306-25810-00-98	306-25810-01-98	*Caliper Assy	1	Yes
35-0-6	306-20000-50	306-20000-51	Caliper Seal Kit	1	No
35-44	306-25826-00-00	306-25826-01-00	..BOLT, Bridge J	2	N/A separately

(*) NOTE: CALIPER ASSY.: As soon as the old type runs out of stock, only the new will be sold.

SEAL KIT: Both the old and new types will continue to be sold.

PLEASE BRING YOUR PARTS LISTS UP TO DATE